

NOTE:
* ASTERISK INDICATES GOV'T FURN MATERIAL

C.O. #91876

LET	ALTERATION	DATE	BY
A	[illegible] WAS 3 [illegible] TURNED EQUIPMENT [illegible] AND SO THAT RECEPTACLE POINTS AFT.	[illegible]	
B	[illegible] ADDED [illegible] & NOTE "[illegible]" 28F3066 (REF)	[illegible]	

C.O. #83648
C.O. #33648

LOCALIZER SIGNAL CONVERTER CDE20109			1			
AN526D1032-10			4			
AC365D1032			4			
Q816-D6-6			1			
Q812-D6-6			4			
Q908-810-8			1			
Q8106-D10-10			1			
PART NO.	STOCK	MATERIAL	SPEC.	REQ. -0	REQ. -2	REQ. -3

PARTS LIST PER ASSY.

MODEL	NEXT ASSY	REQ.
PB2Y-5R	28F6002	1
PBY-5	28F1002	1

REQUIREMENTS PER AIRPLANE

SCALE 12" = 1'-0"

LIMITS 1/32

STAMP PART NUMBER WHERE SHOWN

DRAFT: OLSON 9/30/41 — CHECK: RWS — STRESS: GFRW

NAME: INST.-FURNS.-LOCALIZER SIGNAL CONVERTER MOUNT.

SIZE J — 28F6164

CONSOLIDATED AIRCRAFT CORP. SAN DIEGO, CALIF.

S.O. 953-7 88476
S.O. 949-27-27783
S.O. 936-84-2 70496

H 362